

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS NO. DC-775

1318 VERMONT AVE., NW
(MARY McLEOD BETHUNE HOUSE)
Washington
District of Columbia

HABS
DC
WASH.
529-

Photographer, Jack E. Boucher, July 1993

- DC-775-1 GENERAL VIEW FROM STREET, LOOKING NORTH WEST,
 SHOWING VERMONT AVENUE STREETSCAPE. MARY McLEOD
 BETHUNE HOUSE IS THE THIRD BAY FROM THE LEFT.

- DC-775-2 GENERAL VIEW FROM SIDEWALK, LOOKING NORTH WEST,
 SHOWING VERMONT AVENUE STREETSCAPE. MARY McLEOD
 BETHUNE HOUSE IS THE THIRD BAY FROM THE LEFT.

- DC-775-3 GENERAL VIEW FROM SIDEWALK, LOOKING SOUTH WEST,
 SHOWING VERMONT AVENUE STREETSCAPE. THE MARY
 McLEOD BETHUNE HOUSE IS THE FOURTH BAY FROM THE
 RIGHT.

- DC-775-4 CLOSE UP VIEW OF VERMONT AVENUE STREETSCAPE,
 LOOKING NORTH WEST, MARY McLEOD BETHUNE HOUSE IS
 THE SECOND DOOR FROM THE LEFT.

- DC-775-5 VIEW OF EAST ELEVATION, WITH SCALE

- DC-775-6 VIEW OF EAST ELEVATION, WITHOUT SCALE.

- DC-775-7 CLOSE-UP VIEW OF EAST ELEVATION SHOWING MAIN ENTRY
 AND FRONT BAY DETAILS.

- DC-775-8 DETAIL VIEW OF EAST ELEVATION SHOWING SECOND FLOOR
 WINDOW AND ORNAMENTAL HOOD.

- DC-775-9 DETAIL OF EAST ELEVATION SHOWING CORNICE AND THIRD
 FLOOR DORMER WINDOWS.

- DC-775-10 VIEW OF WEST ELEVATION AND BACK YARD.

- DC-775-11 CLOSE-UP VIEW OF SIDE YARD AND BUILDING ELL.

- DC-775-12 INTERIOR VIEW, FIRST FLOOR, ENTRY HALL, LOOKING EAST TOWARDS MAIN ENTRY.
- DC-775-13 INTERIOR VIEW, FIRST FLOOR, DISPLAY ROOM 1, LOOKING EAST, CLOSE-UP VIEW OF BAY WINDOW.
- DC-775-14 INTERIOR VIEW, FIRST FLOOR, DISPLAY ROOM 1, LOOKING NORTH, SHOWING POCKET SLIDING DOORS.
- DC-775-15 INTERIOR VIEW, FIRST FLOOR, DISPLAY ROOM 1, LOOKING NORTH, PAST POCKET SLIDING DOORS, TO MAIN STAIRCASE.
- DC-775-16 INTERIOR VIEW, FIRST FLOOR, DISPLAY ROOM 2, LOOKING WEST.
- DC-775-17 INTERIOR VIEW, FIRST FLOOR, ENTRY HALL, LOOKING WEST, MAIN STAIRCASE IS ON THE RIGHT.
- DC-775-18 INTERIOR VIEW, SECOND FLOOR, HALLWAY, LOOKING WEST SHOWING MAIN STAIRCASE.
- DC-775-19 INTERIOR VIEW, SECOND FLOOR, HALLWAY, LOOKING WEST, CLOSE-UP VIEW OF ARCHWAY.
- DC-775-20 INTERIOR VIEW, THIRD FLOOR, HALLWAY, LOOKING EAST, SHOWING MAIN STAIRCASE AND A CLOSE-UP VIEW OF BANISTER AND SPINDLES.
- DC-775-21 INTERIOR VIEW, BASEMENT, HALLWAY, LOOKING WEST, SHOWING BOTTOM RUN OF MAIN STAIRCASE.
- DC-775-22 INTERIOR VIEW, FIRST FLOOR, DISPLAY ROOM 1, LOOKING SOUTH, SHOWING CLOSE-UP VIEW OF FIREPLACE.
- DC-775-23 INTERIOR VIEW, SECOND FLOOR, DISPLAY ROOM 3, LOOKING WEST, CLOSE-UP VIEW OF FIREPLACE.

- DC-775-24 INTERIOR VIEW, THIRD FLOOR, OFFICE 2, LOOKING SOUTH,
CLOSE-UP VIEW OF FIREPLACE.
- DC-775-25 INTERIOR VIEW, THIRD FLOOR, OFFICE 3, LOOKING SOUTH,
CLOSE-UP VIEW OF FIREPLACE.
- DC-775-26 INTERIOR VIEW, FIRST FLOOR, ENTRY HALL, DETAIL OF
CHANDELIER AND MEDALLION.
- DC-775-27 INTERIOR VIEW, FIRST FLOOR, DISPLAY ROOM 1, DETAIL OF
CHANDELIER MEDALLION.
- DC-775-28 INTERIOR VIEW, FIRST FLOOR, DISPLAY ROOM 2, DETAIL OF
CHANDELIER MEDALLION.
- DC-775-29 INTERIOR VIEW, SECOND FLOOR, DISPLAY ROOM 3, DETAIL OF
CHANDELIER AND MEDALLION, CHANDELIER ON.
- DC-775-30 INTERIOR VIEW, SECOND FLOOR, DISPLAY ROOM 3, DETAIL OF
CHANDELIER AND MEDALLION, CHANDELIER OFF.
- DC-775-31 INTERIOR VIEW, SECOND FLOOR, HALLWAY, DETAIL OF
MEDALLION, WITH SCALE.
- DC-775-32 INTERIOR VIEW, SECOND FLOOR, HALLWAY, DETAIL OF
MEDALLION, WITHOUT SCALE.
- DC-775-33 INTERIOR VIEW, BASEMENT, VIEW LOOKING WEST SHOWING
BACK STAIRCASE.

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO:

HABS DC-775

1318 VERMONT AVENUE, NORTHWEST (HOUSE)

(Mary McLeod Bethune House)

Mary McLeod Bethune Council House National Historic Site

Washington

District of Columbia

Photos HABS-DC-775-1 through HABS DC-775-33 were previously transmitted to the Library of Congress.

INDEX TO COLOR TRANSPARENCIES

Jack E. Boucher, photographer,

DC-775-34 (CT)	Close Up View Of Vermont Avenue Streetscape, Looking North West, Mary McLeod Bethune Council House National Historic Site Is The Second Door From The Left.
DC-775-35 (CT)	View Of East Elevation Without Scale